11935



NABL, A constituent Board of Quality Council of India, Govt. of India


Management System : As per ISO/IEC 17025:2017

CORPORATE IDENTITY NUMBER: U71200WB2023PTC262957

CORPORATE OFFICE 256A, M. G. Road, Purbasan, Thakurpukur, Kolkata - 700063

LABORATORY: 256A, M. G. Road, Purbasan, Thakurpukur, Kolkata - 700063 Contacts: (033) 2497 1903, M (+91) 9830020628 / M (+91) 9432219707

E-mall: omegalabinfo98@gmail.com



This is to certify that the above sample (S) has/have been tested with the following results:

CHEMICAL ANALYSIS

I. Building Material:

Pozzolanic materials:

Characteristics	Findings	Req. as per IS:15388-2003, Reaf:2022	Test Method
1. Silica as SiO ₂ , (%)	86.02	85.00 Min	IS:1727:1967 Reaf:2018
2. Moisture Content, (%)	0.89	3.00 Max	IS:15388-2003, Reaf:2022
3. Loss on Ignition, (%)	2.8	4.00 Max	IS:1727:1967 Reaf:2018
4. Sodium Oxide as Na ₂ O, (%)	Awaited	Not Specified	IS:15388-2003, Reaf:2022
5. Potassium Oxide as K ₂ O, (%)	Awaited	Not Specified	
6. Alkalis as Na ₂ O, (%)	Awaited	1.5 Max.	

Remarks: The above submitted sample was duly tested as per relevant specification.

Prepared by

♦♦♦♦ End of report ♦♦♦♦

For OMEGALAB TESTING SERVICES PVT, LTD.

04.06.2025

I. MUKHERJEE (BANERJEE) DEPUTY QUALITY MANAGER (AUTHORISED SIGNATORY-CHEM.)

Note:

* "#" denote the information are supplied by customer.

* Decision Rule applied as per OTSPL/QMSP-10 (wherever applicable)

* The test report relates to the Sample(s) submitted by Customer.

Liability for return of sample(s) ceases after fifteen days unless adviced by concerned authority.

* The reproduction of the report except in full is invalid without written approval of the laboratory management.

* The test results referred in test report are based on observations & measurements under the stated environmental conditions.

megalab Testing Services Pot. L.